

Oil Field Environmental Incident Summary

Incident: 20150218182711 **Date/Time of Notice:** 02/18/2015 18:27

Responsible Party: MUREX PETROLEUM CORPORATION

Well Operator: MUREX PETROLEUM CORPORATION

Well Name: MARGARET ELIZABETH 4-33H

Field Name: MCGREGOR

Well File #: 20198

Date Incident: 2/17/2015 **Time Incident:** 15:00

Facility ID Number:

County: WILLIAMS

Twp: 158

Rng: 95

Sec: 4

Qtr: SE SW

Location Description:

Submitted By: William Jansky

Received By:

Contact Person: Shannon Holter
363 N. Sam Houston Pkwy. E.
Suite 200
HOUSTON, TX 77060

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	2	Barrels	2	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 7/14/2015

Clean Up Concluded: 2/18/2015

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Debris cleared, and lines thawed. a Methanol pot was installed on the by-pass line. Impacted soil in the flare pit will be treated after thaw.

Wastes Disposal Location: production tank.

Agencies Involved:

Updates

Date: 2/20/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an unspecified cause, remained on location according to the report. NDIC retains oversight.